

PICARD Bangladesh Ltd.


1143&1145, Konabari, Kashimpur Road, Gazipur
(23.910861N, 90.302220E)

3rd November 2015




Observations

Discrepancies between site observations and information on drawings



Columns are not shown in Architectural Drawing for 7th Floor Presented in Structural Drawing and found in Present Condition.

Poor Construction Work on Roof Shuttering



Poor Construction Work on Roof Shuttering causes uneven Slab Surface

Missing Shock Absorptive Measures on Generator Room



Missing Vibration Absorbers on Generator Room

Priority Actions

Problems Observed

ITEM 1: Missing vibration absorbers below generators.

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Missing vibration absorbers in generator room.	Building Engineer to review generator room slab and consult with generator manufacturers necessary vibration absorber devices.	6-weeks