

MTM GARMENTS LTD.

15934/16004 Chandpara, Medical Road, Uttarkhan
(23.877554N,90.434111E)


4th November 2015



Observations

Lack of vertical bracing

Observations



Lack of vertical bracing



Observations – Production Shed



Connections for bracing unused

Observations – Production Shed

Poorly constructed / installed hangers

Observations



Holes drilled into purlins and hangers welded on




Hangers hooked on purlin lateral restraints

Observations – Production Shed

Cracking in walls

Observations



Observations – Office Building



Crack recently painted over

Observations – Office Building



Cracks in façade on cantilever

Observations – Office Building

Priority Actions

Problems Observed

ITEM 1: Lack of vertical bracing

ITEM 2: Poorly constructed / installed hangers

ITEM 3: Cracking in walls

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Lack of vertical bracing	Building Engineer to check lateral stability of the buildings	6-weeks
2	Lack of vertical bracing	Missing vertical bracing should be completed	6-weeks
3	Lack of vertical bracing	Make structural alterations if required as advised by Engineer	6-months
4	Poorly constructed / installed hangers	Remove all suspensions to the bracings and do a proper connection to the main / secondary structural elements	6-months
5	Poorly constructed / installed hangers	Repair burnouts in the purlins	6-months
6	Cracking in walls	Repair the cracks	6-months