

FIRE SAFETY INSPECTION REPORT

**4A YARN DYEING LTD.
KAICHABARI, SAVAR**

OTHER FACTORIES: NONE



ACCORD
on Fire and Building Safety in Bangladesh



March 24, 2014

SUMMARY

4A Yarn Dyeing Ltd. was surveyed for fire safety on 3/24/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.